
TRI-CHEM

QUICK PATCH Fast Cure Patch

DESCRIPTION (

Quick Patch is a 2-part acrylic acrylate fast cure patch or leveling compound which is used to fill large cracks and depressions in severely damaged concrete from a thickness of 1/8" and up. It is ideal for use in heavy industrial and manufacturing areas where a tough, durable surface is required without a long cure time.



DIRECTIONS

- 1. All oils, greases, chemical deposits, paints, adhesives, and cement surface latents must be removed. Exposed steel reinforcements should be cleaned free from rust.
- 2. Substrate must not have a moisture content greater than 15% by volume.
- 3. Pour contents of Part A (2-quart cans) into overpack container.
- 4. Stir contents of Part B (31-pound bag) into Part A.
- 5. Mix until uniform.
- 6. For small patches, mix 5 parts by volume of Part B to 1 part by volume Part A

Note: This kit will yield approximately 35lbs. of patching material when mixed in its entirety.

FIRST-AID

Eyes: Flush with copious amounts of water lifting lids and removing contact lenses to ensure complete irrigation—get medical attention.

Skin: Flush with water and then wash with soap and water, launder contaminated clothing before reuse—get medical attention if irritation persists.

Inhalation: Remove to fresh air and assist breathing as necessary—get medical attention.

Ingestion: Do NOT induce vomiting. Give water to rinse mouth. Get medical attention.

CAUTION

Please refer to the SDS for more detailed precautionary measures, handling instructions and emergency procedures. KEEP OUT OF REACH OF CHILDREN.